13. The distance of the school building at following distance from the following strategic places:

20 Km. (approx)

Hajipur Railway Junction: (a) 1.5 Km. Nearest Railway Station (b) 2Km. Bus stand (c) 20 Km. Nearest Fire Office (d) 03 Km. Nearest Hospital (e) 1.5 Km. Nearest Nationalized bank (f) 20 Km. Head Post Office (g) 1.5 Km. (h) Post Office 1.5 Km. Nearest Police Station

Electric & water supply is available continuous. The building is constructed as RCC (M-15) Frame structure on Pile foundation wall with first class brick & C.M. (1:6), patent stone flooring, Good quality of wood (sal/sisam) work in doors and windows. Thus, the building seems secured and safe. The school building is situated in good environmental safe zone of the rural area. The (G+2) Map / Plan prepared by Er. Jitendra Kumar, Civil Consultant bearing Lic. No.- E-15/2005 is provided by the management of the school is enclosed.

I, the undersigned, inspected the campus & building of the school on 02.03.2015 and found the above mentioned details are true. The location of the school building appears most suitable for teaching environment.

PAM KUMAR

Pred Valuer & Estimator

Pred Valuer & Estimator

Proved Valuer & Estimator

Proved Valuer & Valuere

Seal & Sign.

Date: 04.03. 2015

श्री लक्ष्मी नारायण सरस्वती विद्या मंदिर 'णवानपुर (वैशाली) Mithelich frough

श्री लक्षी नारायण सरस्वती विद्या मंदिर भगवानपुर, वैज्ञाली

Er. Ram Kumar,

B.E.(Civil), S.L.A. F.I.V.
(Surveyor-Loss-Assessor) & Approved / Panel Valuer,
Estimator, Planner, (SLA-45459/94) & (F-20999, L.M. Cat-I)
[Under- I.R.D.A. (Govt. of India) & By | Institution of Valuers (India)]

Mob: 9835276428

H.Q.- Srikrishna Vihar Colony, South
of Yadavnagar gate, Near- Chauraha
Bhagwanpur, Muzaffarpur-842001
ph - 0621-3209716

Ref. R.K./Craft-2/ S.L.N.S.V.M./ Vaishali/101/2014-15

Date. .04.03.2015

I, on personal request of secretary, "Sri Laxmi Narayan Sarswati Shishu/Vidya Mandir", Bhagwanpur Vaishali, Bihar visited the campus of Sri Laxmi Narayan Sarswati Shishu/Vidya Mandir, Bhagwanpur, Vaishali on 2nd March 2015 and found that it was housed in pukka building with three store (G+2). The building has proper arrangement of water supply, sanitation, drainage outlet, electrification and other needful fitting with required specifications. The details of all campus arrangements are as under:-

camp	CAMPUS &	BUILI	DINGS
01.	Area of campus		10488.03 Sq. mt.
			1085+545+485=2115 S Mt.
02.	Built-up Area (G+1+1)	11:08	9402.76 Sq. mt.
03.	Area of playground		(24+2+1)=27
04.	Total no. of Class room		10 (20×25)
05.	Number of class rooms with dimens	ion:	
06.	Principal Room		1 (20×25)
07.	Office-cum Staff room		01(20×25)
08.	Guard room		01 (10 × 14)
09.	Details of class rooms		
	(a) Area of class room		20×25
	(b) Height of class room		13'-0"
	(c) Av. space provided per student	10 300	1.04 Sq.mt.
10.	Other rooms with dimension	:	
	(a) Composite Science Lab.		$1(30 \times 40)$
	(b) Computer Science Lab.	2/10	1 (30×40)
	(c) Library	:	1 (30×40)
	(d) Maths Lab.		1 (20×25)
	(e) Sports & Games room		1 (20×25)
	(f) Music Room	:	1 (20×25)
	(g) Common Room	:	1 (20×25)
	(1) Other rooms	1	07
	(n) Other rooms	RCCv	vall and iron gate for examination documents -01
11.	Arrangement for safe custody with		
12.	Laboratory & Urinals		04
	(a) For staff		05
	(b) For boys		05
	(c) For girls		16
	(d) Water supply taps	-	10

03

श्री लक्ष्मी नारा ए सरस्वती विद्या मंदिर "गवानपुर (वैशार्)

(d) Water supply taps

(e) Water purifier

सिरियो क्रिया मंदिर भगवानपुर, वैशाली